## Approved For Release 2002/09/03 : CIA-RDP63-00313A000500130083-2

NRO REVIEW COMPLETED	С. ру
	13 September 1963

: Daily Activity Report - 13 September 1963

MEMORANDUM FOR: Deputy Director for Science and Technology

## 1. Mission Status

SUBJECT

25X1

- a. IDEALIST The U-2 detachments at Edwards Air Force Base, California on standby status.
- b. BRASS KNOB One U-2 mission No. 3719 was flown on 12 September with results being 15% target coverage and no reactions indicated.
  - c. SATELLITES No activity.
- 2. OXCART Flights, 12 September:
- a. Aircraft #121 made flight #80, duration 39 minutes, program roughness investigation, maximum speed was Mach . 9, maximum altitude 36,000 feet. Left engine afterburner was surging and torching and cancelled the program. Investigating to determine cause of trouble.
- b. Aircraft #124 made flights #136 and #137 for a duration of 1:59 hours and 1:31 hours. Programs in flight refueling training. Several dry contacts and one wet 8000 pound fuel transfer was completed satisfactorily on each flight.
- 3. OXCART Status, 12 September:
- a. Aircraft #122: Developed engine ignition trouble on start.

  Cause of the trouble was determined to be a plugged chemical ignition proble. Procedure calls were made for periodic inspection and "as required" replacement of these probes

Approved For Release 2002/09/03 - CIA-RDP63-00313A000500130083-2

25X1

25X1

Approved For Release 2002/09/03: CIA-RDP63-00313A000500130083-2

## RETERET



25X1

- b. Aircraft #125: Engine afterburner failed to light at take-off position. Cause of trouble was determined to be a plugged afterburner chemical ignition probe. Procedure calls for periodic inspection were made and "as required" replacement of these probes.
  - c. Aircraft #126: There was a fin replacement.
  - d. Aircraft #127: Is waiting hardware for fin replacement.
  - e. Aircraft #128: Final assembly, ninth week.
  - f. Aircraft #129: Final assembly, second week.

\$